

## **TOWER-1A: TERRACE FLOOR SLAB**



**TOWER NO: 1A (Overall completion 73.70%)**

**Total Floors:** - Stilt + 12 Upper floors

**Total Flats:** - 24 (Duplex Type-A1)

### **PROGRESS:**

1. Structural works up to terrace floor slab completed.
2. 12<sup>th</sup> floor concrete block masonry work completed & terrace floor parapet wall block masonry work completed.
3. Staircase headroom column concrete work completed and head room slab concrete work completed. Head room block work, lift machine room and OHT work in progress.
4. Internal wall and ceiling plastering work completed upto 12<sup>th</sup> floor.
5. Door frame fixing work completed upto 4th floor.
6. Internal waterproofing work completed upto 12<sup>th</sup> floor.
7. Tiling work completed upto 6<sup>th</sup> floor, 7<sup>th</sup> floor in progress.
8. 3<sup>rd</sup> and 4<sup>th</sup> floor toilet flooring and wall dadoing work in progress.
9. Balcony railing work completed upto 10<sup>th</sup> floor. 11<sup>th</sup> floor in progress.
10. Internal staircase railing work completed upto 12<sup>th</sup> floor.
11. Internal wall electrical Conduiting work completed upto 12<sup>th</sup> floor. 1<sup>st</sup> floor Internal electrical wiring work completed.
12. Internal plumbing work (CPVC) and (SWR PVC) pipe work completed upto 12<sup>th</sup> floor.
13. External plastering work (South, East, West, North side) in progress.
14. Door shutters fixing work completed upto 3<sup>rd</sup> floor.
15. 1<sup>st</sup> to 4<sup>th</sup> floor internal wall putty work (first coat) in progress.

## **PROGRESS MYSORE AS ON 15 MARCH 19**

# **TOWER-1B: TERRACE FLOOR SLAB**



**TOWER NO: 1B (Overall completion 73.90%)**

**Total Floors:** - 2 Stilts + 12 Upper floors

**Total Flats:** - 24 (Duplex Type-A1)

### **PROGRESS:**

1. Structural works up to Terrace floor slab completed. Lift machine room and OHT in progress.
2. Terrace floor parapet wall block masonry work completed.
3. Concrete block masonry work completed upto 12th floor.
4. Internal wall and ceiling plastering work completed upto 12<sup>th</sup> floor.
5. Tiling work completed upto 8<sup>th</sup> floor.
6. 9<sup>th</sup> floor door frame fixing work in progress.
7. Balcony railing work completed upto 10<sup>th</sup> floor.
8. Internal staircase railing work completed upto 10<sup>th</sup> floor. 11<sup>th</sup> floor in progress.
9. 1<sup>st</sup> and 2<sup>nd</sup> floor internal staircase cuddapah stone work in progress.
10. Internal waterproofing work completed upto 12<sup>th</sup> floor.
11. Internal wall electrical Conduiting work completed upto 12<sup>th</sup> floor.
12. Internal plumbing (CPVC) work completed upto 12<sup>th</sup> floor, and internal (SWR PVC) pipe work completed upto 12<sup>th</sup> floor.
13. External plastering work (South, East, West, North side) in progress.
14. 3<sup>rd</sup> floor toilet wall dadoing work in progress.
15. 1<sup>st</sup> to 7<sup>th</sup> floor door shutter fixing work in progress.
16. 1<sup>st</sup> to 4<sup>th</sup> floor internal wall putty work (first coat) in progress.

## **TOWER-1C: TERRACE FLOOR SLAB**



**TOWER NO: 1C (Overall completion 67.10%)**

**Total Floors:** - Stilt + 12 Upper floors

**Total Flats:** - 24 (Duplex Type-A1)

### **PROGRESS:**

1. Structural work south side upto 12<sup>th</sup> floor slab concrete work completed & 12<sup>th</sup> floor north side half roof slab beam shuttering work in progress.
2. Concrete block masonry work completed upto 11<sup>th</sup> floor.
3. 10<sup>th</sup> floor internal wall plastering work in progress.
4. Tiling work completed upto 4<sup>th</sup> floor, 5<sup>th</sup> floor in progress. 4<sup>th</sup> floor toilet dadoing work in progress.
5. 1<sup>st</sup> and 2<sup>nd</sup> floor internal staircase cuddapah stone work in progress.
6. 8<sup>th</sup> and 9<sup>th</sup> floor internal waterproofing work in progress.
7. 3<sup>rd</sup> & 4<sup>th</sup> floor door frame fixing work in progress
8. Balcony railing work upto 10<sup>th</sup> floor completed.
9. Internal Staircase railing work completed upto 6<sup>th</sup> floor, 7th floor in progress.
10. 10<sup>th</sup> floor internal wall electrical Conduiting work in progress.
11. Internal plumbing (CPVC) work completed upto 10<sup>th</sup> floor, internal (SWR PVC) pipe work completed upto 8<sup>th</sup> floor.
12. External plastering work (South, East, North and West side) in progress.
13. 1<sup>st</sup> and 2<sup>nd</sup> floor internal wall putty work in progress.

## PROGRESS MYSORE AS ON 15 MARCH 19

# TOWER-2B: TERRACE FLOOR SLAB



**TOWER NO: 2B (Overall completion 63.30%)**

**Total Floors: - 2 Stilts + 12 Upper floors**

**Total Flats: - 48 (Simplex Type-A2)**

### **PROGRESS:**

1. Structural works completed upto terrace floor.
2. Staircase headroom slab completed. Lift machine room and OHT work in progress.
3. Concrete block masonry work completed upto 12<sup>th</sup> floor and terrace floor parapet wall block masonry work completed.
4. 11<sup>th</sup> and 12<sup>th</sup> floor internal plastering work in progress.
5. Tiling work completed upto 6<sup>th</sup> floor, 3<sup>rd</sup> and 4<sup>th</sup> floor toilet wall dadoing work in progress.
6. Balcony railing work upto 10<sup>th</sup> floor completed.
7. Door frame fixing work completed upto 6<sup>th</sup> floor, 7<sup>th</sup> floor in progress.
8. Internal wall electrical conduiting work completed upto 10<sup>th</sup> floor. 11<sup>th</sup> floor in progress.
9. Internal plumbing (CPVC) work completed upto 12<sup>th</sup> floor, Internal (SWR PVC) pipe work completed upto 8<sup>th</sup> floor.
10. Internal wall putty work 2<sup>nd</sup> to 5<sup>th</sup> floor in progress.
11. Door shutters upto 6<sup>th</sup> floor fixing work in progress.

## **PROGRESS MYSORE AS ON 15 MARCH 19**

# **TOWER-2C: TERRACE FLOOR SLAB**



**TOWER NO: 2C (Overall completion 61.10%)**

**Total Floors:** - Stilt + 12 Upper floor

**Total Flats:** - 48 (Simplex Type-A2)

### **PROGRESS:**

1. Structural work completed upto terrace floor.
2. Staircase head room slab completed. Lift machine room and OHT work in progress.
3. 11<sup>th</sup> and 12<sup>th</sup> floor concrete block masonry work in progress.
4. 6<sup>th</sup> floor Tiling work in progress, 3<sup>rd</sup> floor toilet wall dadoing work in progress.
5. Internal waterproofing work completed upto 10<sup>th</sup> floor.
6. Balcony railing work completed upto 10<sup>th</sup> floor.
7. 7<sup>th</sup> floor door frame fixing work in progress.
8. 10<sup>th</sup> floor internal wall electrical Conduiting work in progress.
9. Internal plumbing (CPVC) work completed upto 10<sup>th</sup> floor, internal (SWR PVC) pipe work completed upto 10<sup>th</sup> floor.
10. 1<sup>st</sup> to 5<sup>th</sup> floor door shutters fixing work in progress.
11. 9<sup>th</sup> to 12<sup>th</sup> floor internal wall and ceiling plastering work in progress.

## **PROGRESS MYSORE AS ON 15 MARCH 19**

### **BLOCK-3: SUB STRUCTURE**



**BLOCK NO: 3 (Overall completion 13.80%)**

**Total Floors: - Stilt + 3 Upper floor**

**Amenities: - Club House & Swimming Pool**

#### **PROGRESS:**

- 1. Function hall entrance columns concrete work completed.**
- 2. UG sump tank - Retaining wall waterproofing work in progress.**
- 3. Back filling work in progress.**
- 4. Swimming pool area retaining wall shuttering work in progress.**
- 5. Plinth beam reinforcement and shuttering work and concrete work in progress.**
- 6. Pump room slab shuttering and reinforcement work in progress.**

## PROGRESS MYSORE AS ON 15 MARCH 19

# BLOCK-5: TERRACE FLOOR SLAB



**BLOCK NO: 5 (Overall completion 73.90%)**

**Total Floors:** - Stilt + 10 Upper floors

**Total Flats:** - 40 (Simplex Type B-II)

### **PROGRESS:**

1. Structural works up to terrace floor slab completed.
2. Staircase head room shuttering and bar bending work and lift machine room Concrete work in progress.
3. Concrete block masonry work completed upto 10th floor & Terrace floor parapet wall block masonry work completed.
4. Internal wall and ceiling plastering work completed upto 10<sup>th</sup> floor.
5. 7<sup>th</sup> floor tiling work in progress, 5<sup>th</sup> floor toilet wall dadoing work in progress.
6. Balcony railing work completed upto 10<sup>th</sup> floor.
7. Water proofing work completed upto 10th floor.
8. 10<sup>th</sup> floor door frame fixing work in progress.
9. Internal wall electrical Conduiting work completed upto 10<sup>th</sup> floor. 1<sup>st</sup> floor internal Electrical wiring work in progress.
10. Internal plumbing (CPVC) work completed upto 10<sup>th</sup> floor, internal (SWR PVC) pipe work Completed upto 10<sup>th</sup> floor.
11. External plastering work (North side, Westside, Eastside, and Southside) in progress.
12. 1<sup>st</sup> to 5<sup>th</sup> floor door shutters fixing work in progress.
13. 1<sup>st</sup> to 5<sup>th</sup> floor internal wall putty work in progress.

## PROGRESS MYSORE AS ON 15 MARCH 19

# RETAINING WALL



### RETAINING WALL- NORTH AND WEST SIDE

#### **PROGRESS:**

1. Earth work excavation in progress. North side 88% and west side 93% completed.
2. PCC concrete work in progress. North side 82% and west side 93% completed.
3. Footing and wall reinforcement work in progress. North side 46% and west side 93% completed.
4. Footing and wall concreting work in progress. North side 31% and west side 91% completed.
5. Retaining wall concreting work in progress. North side 14% completed, west side yet to commence.

## **PROGRESS MYSORE AS ON 15 MARCH 19**

# COMPOUND WALL



### **COMPOUND WALL- SOUTH SIDE**

#### **PROGRESS:**

- 1. Earth work excavation completed.**
- 2. PCC concrete work completed.**
- 3. Plinth beam work completed.**
- 4. Block work in progress. 91% work completed.**
- 5. Outside plastering work in progress. 36% work completed.**

**PROGRESS MYSORE AS ON 15 MARCH 19**

## **MAIN ENTRANCE GATE**



### **MAIN ENTRANCE GATE- SOUTHSIDE (NEAR BLOCK-3)**

#### **PROGRESS:**

- 1. Earth work excavation completed.**
- 2. PCC concrete work completed.**
- 3. Footing and Plinth beam work completed.**
- 4. Column reinforcement work and column starter concreting work completed.**
- 5. Column shuttering work and concreting work yet to commence.**