

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018

## WEB UP DATE FOR AFNHB BHUBANESWAR PROJECT

### Progress Update:

1. Dismantling and removing of Tools & machineries of old contractor is in progress,
2. **External Development Works** Roads, drains, cable laying, fixing of street lights etc in progress.
3. **Lifts Work** Commissioning of Lifts has been completed in 04 blocks.
4. **Swimming Pool** Civil work completed, finishing work commenced.
5. **STP** Civil work completed, mechanical work in progress
6. **Towers** Balance works of Firefighting, internal wirings, Paintings, Doors window fixing in few flats are in progress. No major works pending, Testing and commissioning of all service commenced.

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018

AVERAGE DAILY LABOUR IN FEB 2017- MAR 2018: 243



**TOWER NO: A OFFICERS (Overall completion-95.80%)**

Total floors: S1+S2+8

Total Flats: 32

**PROGRESS:**

CHINA WARE FITTING	- 95% completed
PAINTING (INTERNAL)	- 100% (1st coat paint completed)
EXTERNAL PAINT	- 80% completed
ELECTRICAL WORK	- 93% completed
DOOR & WINDOW FIXING	- 90% completed
FIRE FIGHTING WORK	- 55% completed
CP FITTING	- 85% completed

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018



## **TOWER NO: B OFFICERS (Overall completion-92.51%)**

Total floors: S1+S2+8

Total Flats: 32

### **PROGRESS:**

<b>PLUMBING</b>	- 80% completed
<b>EXTERNAL PAINT</b>	-80% completed
<b>ELECTRICAL WORK</b>	- 85% completed
<b>FIRE FIGHTING WORK</b>	- <b>55% completed</b>
<b>DOOR &amp; WINDOW FIXING</b>	- 60% completed
<b>CHINA WARE FITTING</b>	- 90% completed

## PROGRESS BHUBANESWAR AS ON 26 MAR 2018



**TOWER NO:** C OFFICERS (Overall completion-**93.85%**)

Total floors: S1+S2+8

Total Flats: 32

**PROGRESS:**

<b>PLUMBING</b>	- 90% completed
<b>CHINA WARE FITTING</b>	- 90% completed
<b>EXTERNAL PAINT</b>	-80% completed
<b>ELECTRICAL WORK</b>	- 85% completed
<b>DOOR &amp; WINDOW FIXING</b>	- 60% completed
<b>FIRE FIGHTING WORK</b>	- <b>55% completed</b>

## PROGRESS BHUBANESWAR AS ON 26 MAR 2018



### **TOWER NO: D OFFICERS (Overall completion-94.85%)**

Total floors: S1+S2+8

Total Flats: 32

### **PROGRESS:**

<b>CHINA WARE FITTING</b>	- 90% completed
<b>EXTERNAL PAINT</b>	-80% completed
<b>ELECTRICAL WORK</b>	- 90% completed
<b>DOOR &amp; WINDOW FIXING</b>	- 60% completed
<b>FIRE FIGHTING WORK</b>	- 55% completed
<b>CP FITTING</b>	-60% completed
<b>FALSE CEILING</b>	-100% Completed

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018



## **TOWER NO: E SAILOR (Overall completion-89.31%)**

Total floors: S1+S2+11

Total Flats: 43

### **PROGRESS:**

<b>EXTERNAL PAINT</b>	- 90% completed
<b>PLUMBING</b>	- 80% completed
<b>ELECTRICAL WORK</b>	- 80% completed
<b>FIRE FIGHTING WORK</b>	- 55% completed
<b>DOOR &amp; WINDOW FIXING</b>	- 50% completed
<b>CHINA WARE FITTING</b>	- 90% completed
<b>STAIRCASE RAILING</b>	-10% completed

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018



## **TOWER NO: F SAILOR (Overall completion-87.45%)**

Total floors: S1+S2+11

Total Flats: 43

### **PROGRESS:**

<b>TILING</b>	- 95% completed
<b>PLUMBING</b>	- 80% completed
<b>EXTERNAL PAINT</b>	-90% completed
<b>ELECTRICAL WORK</b>	- 75% completed
<b>FIRE FIGHTING WORK</b>	- 50% completed
<b>DOOR &amp; WINDOW FIXING</b>	- 50% completed
<b>STAIRCASE RAILING</b>	-40% completed
<b>FALSE CEILING</b>	-85% Completed

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018



## **TOWER NO: G SAILOR (Overall completion-97.05%)**

Total floors: S1+S2+11

Total Flats: 42

### **PROGRESS:**

<b>EXTERNAL PAINT</b>	- 80% completed
<b>CHINA WIRE FITTING</b>	- 80% completed
<b>ELECTRICAL WORK</b>	- 87% completed
<b>FIRE FIGHTING WORK</b>	- 50% completed
<b>CP FITTING</b>	- 85% completed

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018



**TOWER NO: COMMUNITY CENTER (Overall completion-**94.86%**)**

Total floors: G+1

## **PROGRESS:**

<b>BRICK WORK</b>	- 90% completed
<b>PAINTING</b>	- <b>100% (1<sup>st</sup> coat paint completed)</b>
<b>ELECTRICAL WORK</b>	- <b>80% completed</b>
<b>FIRE FIGHTING WORK</b>	- <b>30% completed</b>
<b>DOOR &amp; WINDOW FIXING</b>	- 30% completed
<b>EXTERNAL PAINT</b>	- <b>85% completed</b>
<b>TILING</b>	- <b>70% completed</b>

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018

## SWIMMING POOL



**SWIMMING POOL-** (Overall completion- 55%)

**PROGRESS:** Wall plastering completed & Accessories reached at site.

## PROGRESS BHUBANESWAR AS ON 26 MAR 2018

### LIFT WORK



### LIFT WORK (Overall completion- 75%)

PROGRESS: 14 Nos lift material has arrived at site. And 10 nos lift work in progress all block

Lift commissioning completed A, D, E & G block.

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018

## EXTERNAL DRAIN WORK



**EXTERNAL DRAIN WORK** (Overall completion- 90%)

**PROGRESS:** Raft & Wall casting work in progress.

## PROGRESS BHUBANESWAR AS ON 26 MAR 2018

### FIREFIGHTING WORK



### FIREFIGHTING WORK

PROGRESS: Sprinkler line painting.

## PROGRESS BHUBANESWAR AS ON 26 MAR 2018

### EXTERNAL ROAD & RETAINING WALL WORK



### EXTERNAL ROAD & RETAINING WALL WORK (Overall completion- 85%)

PROGRESS: VDF flooring work in progress.

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018

## RECHARGE PIT



RECHARGE PIT (Overall completion- 75%)

PROGRESS: Cover casting work in progress.

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018

## PUMP ROOM



## PUMP ROOM

PROGRESS: Installation completed & testing work in progress.

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018

## EXTERNAL ELECTRICAL WORK AT CESU PREMISES (A)



**CABLE TRENCH COVERING IN SIDE AFNHB**



**CABLE END TERMINATION IN SIDE AFNHB**



### EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 90%)

#### PROGRESS:

All works completed

**AB CABLE**

-90% completed

# PROGRESS BHUBANESWAR AS ON 26 MAR 2018

## EXTERNAL ELECTRICAL WORK AT AFNHB SITE PREMISES (B)




**CABLE LAYING FROM TRF TO PANEL AT S/S-2**



**CABLE LAYING FROM TRF TO PANEL AT S/S-1**



**COMMON PANEL**



**COMMON PANEL**

### EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 77%)

#### PROGRESS:

<b>CIVIL FOUNDATIONS</b>	- 95% completed
<b>EQUIPMENT ERECTION</b>	- Transformers, DG sets erected
<b>STRUCTURE ERECTION</b>	- FP & TP erected
<b>CABLE LAYING</b>	- 77% completed
<b>CABLE END TERMINATION</b>	- 80% completed
<b>LT PANEL</b>	- 05 nos transformer panel erected
<b>LIGHTNING ARRESTOR</b>	- 70% Completed)
<b>STREET LIGHT</b>	- Pole foundation work started & street light inspection completed
<b>TELEPHONE SYSTEM</b>	- HDPE pipe laying work in progress
<b>TESTING</b>	- IR TEST completed