PROGRESS DEHRADUN AS ON 15 FEB 17 (VIEW OF PACKAGE-II)



Average Strength of labour Jan 17 and Feb17: 530 No's

PROGRESS DEHRADUN AS ON 15 FEB 17 (PACKAGE-II)



TOWER NO: A2B/5 (overall completion 92.28%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

- 100% completed- 100% completed

BRICK WORK

- 100% completed

EXTERNAL PLASTERING INTERNAL PLASTERING

- 100% completed

TILING

- 100% completed

PLUMBING

- 98% completed (except CP fitting)

CHINA WIRE FITTING

- 50% completed

PAINTING

- 60% completed

ELECTRICAL WORK

- 80% completed

DOOR & WINDOW FIXING

- 90% completed

FIRE FIGHTING WORK

- 85% completed



TOWER NO: B2/1 (overall completion 93.23%)

Total Floors: - G+6

Total Flats: - 54 (1298.98 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

- 100% completed

EXTERNAL PLASTERING

- 100% completed

- 100% completed

INTERNAL PLASTERING

- 100% completed

TILING

- 98% completed

PLUMBING

- 95% completed (except CP fitting)

CHINA WIRE FITTING

- 60% completed

PAINTING

- 80% completed

ELECTRICAL WORK

- 90% completed

DOOR & WINDOW FIXING

- 90% completed

FIRE FIGHTING WORK



TOWER NO: B2/2 (overall completion 94.75%)

Total Floors: - G+6

Total Flats: - 53 (1298.98 SF)

PROGRESS: STRUCTURAL WORK

- 100% completed

BRICK WORK

- 100% completed

- 100% completed

EXTERNAL PLASTERING INTERNAL PLASTERING

- 100% completed

TILING

- 98% completed

PLUMBING

- 95% completed (except CP fitting) - 60% completed

CHINA WIRE FITTING

PAINTING ELECTRICAL WORK - 80% completed - 90% completed

DOOR & WINDOW FIXING

- 90% completed

FIRE FIGHTING WORK



TOWER NO: B1/3 (overall completion 89.51%)

Total Floors: - G+6

Total Flats: - 52 (1558.01 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

- 100% completed - 100% completed **EXTERNAL PLASTERING**

INTERNAL PLASTERING TILING

- 100% completed - 90% completed

- 100% completed

PLUMBING

- 92% completed (except CP fitting)

CHINA WIRE FITTING

- 05% completed

PAINTING

- 60% completed - 75% completed

ELECTRICAL WORK DOOR & WINDOW FIXING

- 65% completed

FIRE FIGHTING WORK

- 80% completed



TOWER NO: B1/2 (overall completion 82.24%)

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

100% completed100% completed

EXTERNAL PLASTERING

- 100% completed

INTERNAL PLASTERING TILING

- 92% completed

PLUMBING

- 85% completed

CHINA WIRE FITTING

- 60% completed (except CP fitting)- 05% completed

PAINTING

- 50% completed

ELECTRICAL WORK

- 55% completed

DOOR & WINDOW FIXING

- 20% completed

FIRE FIGHTING WORK

- 50% completed



TOWER NO: B1/1 (overall completion 79.27%)

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING TILING

PLUMBING

CHINA WIRE FITTING

PAINTING ELECTRICAL WORK

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed

- 92% completed

- 60% completed

- 50% completed (except CP fitting)

- 05% completed

- 50% completed

- 50% completed

- 20% completed

- 50% completed



TOWER NO: A2B/4 (overall completion 77.79%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

STRUCTURAL WORK

- 100% completed - 100% completed

BRICK WORK
EXTERNAL PLASTERING

- 95% completed

INTERNAL PLASTERING

- 90% completed

TILING

- 20% completed

PLUMBING

- 50% completed (except CP fitting)

CHINA WIRE FITTING

- 05% completed

PAINTING

- 50% completed

ELECTRICAL WORK

- 50% completed

DOOR & WINDOW FIXING

- 10% completed

FIRE FIGHTING WORK

- 50% completed



TOWER NO: A2B/3 (overall completion 64.48%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING

PLUMBING

CHINA WIRE FITTING

PAINTING

ELECTRICAL WORK

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 95% completed

- 75% completed

- 10% completed

- Nil

- 40% completed

- Nil

- Nil

- 10% completed

- 30% completed

- 30% completed









VIEW OF UPPER BASEMENT ROOF TOP DEVELOPMENT WORK

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING

ROADS

FIREFIGHTING

SEWER LINE

DRAIN LINE

- 100% completed

- 100% completed

- 100% completed

- 100% completed

- 60% completed

- 55% completed

- 54% completed

- 54% completed





VIEW OF LOWER BASEMENT DEVELOPMENT WORK

PROGRESS:

(a) **LOWER BASEMENT:**

STRUCTURAL WORK - 100% completed
INTERNAL PLASTERING - 100% completed
VD FLOORING - 80% completed
FIRE FIGHTING - 80% completed

MECHANICAL VENTILATION - NIL

INTERNAL ELE - 90% completed

(b) <u>UPPER BASEMENT:</u>

STRUCTURAL WORK - 100% completed
INTERNAL PLASTERING - 100% completed
VD FLOORING - 100% completed
FIRE FIGHTING - 90% completed

MECHANICAL VENTILATION - NIL

INTERNAL ELE - 90% completed

PROGRESS DEHRADUN AS ON 15 FEB 17 (PACKAGE-I)

Important: Considering the progress of contractor of Package-I has been given Go Ahead to complete the balance works, including finishing work in each DU and construction of Guard etc. Meeting was held with NG Constructions on 17 Feb 17. Balance work of package I will commence on 01 Mar 17.



TOWER NO: A1/1 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

....

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING

PLUMBING

CHINA WIRE FITTING

PAINTING

ELECTRICAL WORK

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed - 100% completed

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

- 97% completed

- 95% completed



TOWER NO: A1/2 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING

PLUMBING

CHINA WIRE FITTING

PAINTING

ELECTRICAL WORK

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

- 97% completed

- 95% completed



TOWER NO: A1/3 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING PLUMBING

CHINA MAIDE FITTING

CHINA WIRE FITTING

PAINTING

ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK - 100% completed

- 100% completed

- 100% completed - 100% completed

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

97% completed95% completed



TOWER NO: A1/4 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING

PLUMBING

CHINA WIRE FITTING

PAINTING

ELECTRICAL WORK

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

20070 COMPleted

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

- 97% completed

- 95% completed



TOWER NO: A1/5 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING PLUMBING

CHINA WIRE FITTING

PAINTING

ELECTRICAL WORK DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

- 97% completed

- 95% completed



TOWER NO: A2/1 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

- 100% completed- 100% completed

EXTERNAL PLASTERING INTERNAL PLASTERING

- 100% completed

- 100% completed

TILING PLUMBING - 100% completed- 100% completed (except CP fitting)

CHINA WIRE FITTING

- 100% completed

PAINTING

- 100% Completed (except final coat)

ELECTRICAL WORK
DOOR & WINDOW FIXING
FIRE FIGHTING WORK

97% completed95% completed



TOWER NO: A2/2(overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING PLUMBING

CHINA WIRE FITTING

PAINTING

ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed

- 100% completed - 97% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

- 97% completed

- 95% completed