

TOWER-1A: TERRACE FLOOR SLAB



TOWER NO: 1A (Overall completion 74.00%)

Total Floors: - Stilt + 12 Upper floors

Total Flats: - 24 (Duplex Type-A1)

PROGRESS:

1. Structural works up to terrace floor slab completed.
2. 12th floor concrete block masonry work completed & terrace floor parapet wall block masonry work completed.
3. Staircase headroom column concrete work completed and head room slab concrete work completed. Head room block work, lift machine room and OHT work in progress.
4. Internal wall and ceiling plastering work completed up to 12th floor.
5. 5th and 6th floor door frame fixing work in progress.
6. Internal waterproofing work completed up to 12th floor.
7. Tiling work completed up to 6th floor, 7th and 8th floor in progress.
8. 3rd and 4th floor toilet flooring and wall dadoing work in progress.
9. Balcony railing work completed up to 10th floor. 11th floor in progress.
10. Internal staircase railing work completed up to 12th floor.
11. Internal wall electrical conduiting work completed up to 12th floor. 1st floor internal electrical wiring work completed, 2nd floor wiring work in progress.
12. Internal plumbing work (CPVC) and (SWR PVC) pipe work completed up to 12th floor.
13. External plastering work (South, East, West, North side) in progress.
14. Door shutters fixing work completed up to 3rd floor.
15. 1st to 6th floor internal wall putty work (first coat) in progress.
16. External staircase railing work in progress.

TOWER-1B: TERRACE FLOOR SLAB



TOWER NO: 1B (Overall completion 74.20%)

Total Floors: - 2 Stilts + 12 Upper floors

Total Flats: - 24 (Duplex Type-A1)

PROGRESS:

1. Structural works up to terrace floor slab completed. Lift machine room and OHT work in progress.
2. Terrace floor parapet wall block masonry work completed.
3. Concrete block masonry work completed up to 12th floor.
4. Internal wall and ceiling plastering work completed up to 12th floor.
5. Tiling work completed up to 8th floor.
6. Door frame fixing work completed up to 10th floor.
7. Balcony railing work completed up to 10th floor.
8. Internal staircase railing work completed up to 10th floor. 11th floor in progress.
9. 1st and 2nd floor internal staircase cuddapah stone work in progress.
10. Internal waterproofing work completed up to 12th floor.
11. Internal wall electrical conduiting work completed up to 12th floor.
12. Internal plumbing (CPVC) work completed up to 12th floor, and internal (SWR PVC) pipe work completed up to 12th floor.
13. External plastering work (South, East, West, North side) in progress.
14. 3rd floor toilet wall dadoing work in progress.
15. 1st to 8th floor door shutter fixing work in progress.
16. 1st to 4th floor internal wall putty work (first coat) in progress.

TOWER-1C: TERRACE FLOOR SLAB



TOWER NO: 1C (Overall completion 67.30%)

Total Floors: - Stilt + 12 Upper floors

Total Flats: - 24 (Duplex Type-A1)

PROGRESS:

1. Structural work up to terrace floor slab completed. Head room column reinforcement and concrete work in progress.
2. Concrete block masonry work completed up to 11th floor.
3. 10th floor internal wall plastering work in progress.
4. Tiling work completed up to 4th floor, 5th floor in progress. 4th floor toilet dadoing work in progress.
5. 1st and 2nd floor internal staircase cuddapah stone work in progress.
6. Internal waterproofing work completed up to 10th floor.
7. 3rd & 4th floor door frame fixing work in progress.
8. Balcony railing work completed up to 10th floor.
9. Internal Staircase railing work completed up to 6th floor, 7th floor in progress.
10. Internal wall electrical conduiting work completed up to 10th floor.
11. Internal plumbing (CPVC) work completed up to 10th floor, internal (SWR PVC) pipe work completed up to 9th floor.
12. External plastering work (South, East, North and West side) in progress.
13. 1st and 2nd floor internal wall putty work (first coat) in progress.

TOWER-2B: TERRACE FLOOR SLAB



TOWER NO: 2B (Overall completion 63.80%)

Total Floors: - 2 Stilts + 12 Upper floors

Total Flats: - 48 (Simplex Type-A2)

PROGRESS:

1. Structural works completed up to terrace floor.
2. Staircase headroom slab completed. Lift machine room and OHT work in progress.
3. Concrete block masonry work completed up to 12th floor and terrace floor parapet wall block masonry work completed.
4. 12th floor internal plastering work in progress.
5. Tiling work completed up to 6th floor, 3rd and 4th floor toilet wall dadoing work in progress.
6. Balcony railing work completed up to 10th floor.
7. Door frame fixing work completed up to 7th floor, 8th floor in progress.
8. Internal wall electrical conduiting work completed up to 11th floor. 12th floor in progress.
9. Internal plumbing (CPVC) work completed up to 12th floor, internal (SWRPVC) pipe work completed up to 9th floor.
10. Internal wall putty work 2nd to 5th floor (first coat) in progress.
11. 1st floor to 7th floor door shutters fixing work in progress.
12. 11th and 12th floor internal waterproofing work in progress.
13. External plastering work (North, South, West, and East side) in progress.

PROGRESS MYSORE AS ON 15 APRIL 19

TOWER-2C: TERRACE FLOOR SLAB



TOWER NO: 2C (Overall completion 61.50%)

Total Floors: - Stilt + 12 Upper floor

Total Flats: - 48 (Simplex Type-A2)

PROGRESS:

1. **Structural work completed up to terrace floor.**
2. **Staircase head room slab completed. Lift machine room and OHT work in progress.**
3. **11th and 12th floor concrete block masonry work in progress.**
4. **6th floor tiling work in progress, 3rd floor toilet wall dadoing work in progress.**
5. **Internal waterproofing work completed up to 10th floor.**
6. **Balcony railing work completed up to 10th floor.**
7. **7th floor door frame fixing work in progress.**
8. **10th floor internal wall electrical conduiting work in progress.**
9. **Internal plumbing (CPVC) work completed up to 10th floor, internal (SWR PVC) pipe work completed up to 10th floor.**
10. **1st to 5th floor door shutters fixing work in progress.**
11. **10th to 12th floor internal wall and ceiling plastering work in progress.**
12. **External plastering work (North, South, West and East side) in progress.**
13. **First coat internal wall putty work only 2nd floor in progress.**

PROGRESS MYSORE AS ON 15 APRIL 19

BLOCK-3: SUB STRUCTURE



BLOCK NO: 3 (Overall completion 15.30%)

Total Floors: - Stilt + 3 Upper floor

Amenities: - Club House & Swimming Pool

PROGRESS:

- 1. Function hall entrance columns concrete work completed.**
- 2. UG sump tank retaining wall waterproofing work in progress.**
- 3. Back filling work in progress.**
- 4. Swimming pool area retaining wall shuttering work and concrete work in progress.**
- 5. Plinth beam reinforcement and shuttering work and concrete work completed.**
- 6. Pump room slab concrete work completed.**

BLOCK-5: TERRACE FLOOR SLAB



BLOCK NO: 5 (Overall completion 74.20%)

Total Floors: - Stilt + 10 Upper floors


Total Flats: - 40 (Simplex Type B-II)

PROGRESS:

1. **Structural works up to terrace floor slab completed.**
2. **Staircase head room shuttering and bar bending work and lift machine room concrete work in progress.**
3. **Concrete block masonry work completed up to 10th floor & terrace floor parapet wall block masonry work completed.**
4. **Internal wall and ceiling plastering work completed up to 10th floor.**
5. **7th floor tiling work in progress, 5th floor toilet wall dadoing work in progress.**
6. **Balcony railing work completed up to 10th floor.**
7. **Water proofing work completed up to 10th floor.**
8. **Door frame fixing work completed up to 10th floor.**
9. **Internal wall electrical conduiting work completed up to 10th floor. 1st floor internal electrical wiring work in progress.**
10. **Internal plumbing (CPVC) work completed up to 10th floor, internal (SWR PVC) pipe Work Completed up to 10th floor.**
11. **External plastering work (North, West, East, and Southside) in progress.**
12. **1st to 5th floor door shutters fixing work in progress.**
13. **1st to 5th floor internal wall putty work (first coat) in progress.**

PROGRESS MYSORE AS ON 15 APRIL 19

RETAINING WALL



RETAINING WALL- NORTH AND WEST SIDE

PROGRESS:

1. Earth work excavation in progress. North side-90% and west side-97% completed.
2. PCC concrete work in progress. North side-85% and west side-97% completed.
3. Footing and wall reinforcement work in progress. North side-65% and west side-97% completed.
4. Footing concreting work in progress. North side-60% and west side-97% completed.
5. Retaining wall concreting work (first lift) in progress. North side-40% completed and west side not yet commenced.

COMPOUND WALL



COMPOUND WALL- SOUTH SIDE

PROGRESS:

1. Earth work excavation completed.
2. PCC concrete work completed.
3. Plinth beam work completed.
4. Block work in progress. 93% work completed.
5. Outside plastering work in progress. 38% work completed.

PROGRESS MYSORE AS ON 15 APRIL 19

MAIN ENTRANCE GATE



MAIN ENTRANCE GATE- SOUTHSIDE (NEAR BLOCK-3)

PROGRESS:

- 1. Earth work excavation completed.**
- 2. PCC concrete work completed.**
- 3. Footing and Plinth beam work completed.**
- 4. Column reinforcement work and column starter concreting work completed.**
- 5. Column shuttering work and concreting work not yet commenced.**